

HPE Aruba Networking Wireless Operating System 8.12.0.5 Release Notes



Hewlett Packard
Enterprise

Copyright Information

© Copyright 2025 Hewlett Packard Enterprise Development LP.

Open Source Code

This product includes code licensed under certain open source licenses which require source compliance. The corresponding source for these components is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, please check if the code is available in the HPE Software Center at <https://myenterpriselicense.hpe.com/cwp-ui/software> but, if not, send a written request for specific software version and product for which you want the open source code. Along with the request, please send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company
Attn: General Counsel
WW Corporate Headquarters
1701 E Mossy Oaks Rd, Spring, TX 77389
United States of America



Contents	3
Revision History	4
Release Overview	5
Important	5
Related Documents	5
Supported Browsers	5
Terminology Change	6
Contacting Support	6
What's New in AOS-8.12.0.5	8
Supported Platforms	9
Regulatory Updates in AOS-8.12.0.5	13
Resolved Issues in AOS-8.12.0.5	14
Known Issues in AOS-8.12.0.5	20
Limitations in AOS-8.12.x	25
Upgrade Procedure	26
Important Points to Remember	26
RAM and FLASH Storage Requirements	27
Low Free Flash Memory	27
Backing up Critical Data	31
Upgrading AOS-8	33
Verifying the AOS-8 Upgrade	34
Downgrading AOS-8	36
Before Calling Technical Support	38

Chapter 1

Revision History

The following table lists the revision numbers and the corresponding changes that were made in this release:

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

This AOS-8 release notes includes the following topics:

- New Features and Enhancements
- Supported Platforms
- Regulatory Updates
- Resolved Issues
- Known Issues and Limitations
- Upgrade Procedure

Important

- Upgrading to AOS-8.12.0.0 on the 9000 Series and 9200 Series controllers will take longer than usual as we will be automatically upgrading the BIOS version to support additional functionality in the future. This upgrade is estimated to take up to 15 minutes and should not be interrupted for any reason. Power failures and interruptions during the upgrade may make the controller unusable. Please use caution and plan accordingly.



Cluster Rolling Upgrade is not supported when a BIOS upgrade is required. AOS-8 must be manually upgraded for these controllers. In a (very rare) scenario where, post reload command, the unit does not come up in 15-20 minutes, apply power cycle only once and wait for a minimum of 15 minutes without re-applying power cycle again.

- The factory-default image of APs introduced in AOS-8.9.0.0 or later versions use **aruba-conductor** as the host name instead of **aruba-master** to identify a target managed device or stand-alone controller during DNS discovery. However, the factory-default image of APs that were introduced prior to AOS-8.9.0.0 still use **aruba-master** during DNS discovery. The usage of **aruba-conductor** is to align with the Inclusive Language Initiative.

Related Documents

The following guides are part of the complete documentation for the Aruba user-centric network:

- *AOS-8 Getting Started Guide*
- *AOS-8 User Guide*
- *AOS-8 CLI Reference Guide*
- *AOS-8 API Guide*
- *Aruba Mobility Conductor Licensing Guide*
- *Aruba Virtual Appliance Installation Guide*
- *Aruba AP Software Quick Start Guide*

Supported Browsers

The following browsers are officially supported for use with the AOS-8 WebUI:

Web Browser	Operating System
Microsoft Edge (Microsoft Edge 92.0.902.62 and Microsoft EdgeHTML 18.19041) or later	<ul style="list-style-type: none">■ Windows 10 or later■ macOS
Firefox 107.0.1 or later	<ul style="list-style-type: none">■ Windows 10 or later■ macOS
Apple Safari 15.4 (17613.17.1.13) or later	<ul style="list-style-type: none">■ macOS
Google Chrome 108.0.5359.71 or later	<ul style="list-style-type: none">■ Windows 10 or later■ macOS

Terminology Change

As part of advancing HPE's commitment to racial justice, we are taking a much-needed step in overhauling HPE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our HPE culture and moving forward, Aruba will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Main Site	arubanetworking.hpe.com
Support Site	networkingsupport.hpe.com
Airheads Social Forums and Knowledge Base	community.arubanetworks.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	arubanetworks.com/support-services/contact-support
Software Licensing Site	lms.arubanetworks.com

End-of-life Information

arubanetworks.com/support-services/end-of-life

Security Incident Response Team

Site: arubanetworks.com/support-services/security-bulletins

Email: aruba-sirt@hpe.com

Chapter 3

What's New in AOS-8.12.0.5

This chapter describes the features, enhancements, and behavioral changes introduced in this release.

IPSec Tunnels with mandatory Post-Quantum Preshared Key (PPK)

Starting with AOS-8.12.0.5 IPSec tunnels can be set to require PPK configuration on the initiator and responder.

This feature can be enabled by running the [crypto-local isakmp ppk-mandatory](#) command on the responder. When **ppk-mandatory** is enabled, both the responder and initiator are expected to have the PPK configured. Otherwise, the tunnel will not come up. The **ppk-mandatory** parameter will not have any effect if it is enabled on the initiator; it is applicable only on the responder. For more information, visit Configuring a VPN with Postquantum Preshared Keys in the [User Guide](#).

Increased Max ACE Entry Limit

AOS-8.12.0.5 increases the max ACE entry limit up to 16,000 in 9240 platforms.

Chapter 4

Supported Platforms

This section displays the supported platforms in AOS-8.x. The **minimum version supported** column displays the minimum AOS-8.x version that can be run on a platform. The **latest version supported** column displays the newest AOS-8.x version that can be run on a certain device. Patch releases do not affect platform support. For example, a device which **latest supported version** is 8.10.0.x can run on any 8.10.0.x version, such as 8.10.0.2 or 8.10.0.10.

Mobility Conductor Platforms

Mobility Conductor		AOS-8.x Versions Supported	
Conductor Family	Conductor Model	Minimum	Latest
Hardware Mobility Conductor	MCR-HW-1K, MCR-HW-5K, MCR-HW-10K	8.1.0.x	8.13.0.x
Virtual Mobility Conductor	MCR-VA-500, MCR-VA-1K, MCR-VA-5K, MCR-VA-10K	8.0.0.x	8.13.0.x
	MCR-VA-50	8.1.0.x	8.13.0.x

Mobility Controller Platforms

Mobility Controllers		AOS-8.x Versions Supported	
Controller Family	Controller Model	Minimum	Latest
9200 Series	9240	8.10.0.x	8.13.0.x
9000 Series	9012	8.7.0.x	8.13.0.x
	9004	8.5.0.x	8.13.0.x
7200 Series	7280	8.3.0.x	8.13.0.x
	7205, 7210, 7220, 7240, 7240XM	8.0.0.x	8.13.0.x
7000 Series	7005, 7008, 7010, 7024, 7030	8.0.0.x	8.13.0.x
Virtual Mobility Controllers	MC-VA-50, MC-VA-250, MC-VA-1K	8.0.0.x	8.13.0.x
	MC-VA-10	8.4.0.x	8.13.0.x

Access Point Platforms

Access Points			AOS-8.x Versions Supported	
AP Family	AP Series	AP Model	Minimum	Latest
6xx	670 Series	AP-675, AP-675EX, AP-677, AP-677EX, AP-679, AP-679EX	8.12.0.x	8.13.0.x
	650 Series	AP-655A, AP-654A	8.13.0.x	8.13.0.x
		AP-655	8.10.0.x	8.13.0.x
		AP-654	8.11.2.x	8.13.0.x
	630 Series	AP-635A, AP-634A	8.13.0.x	8.13.0.x
		AP-635	8.9.0.x	8.13.0.x
		AP-634	8.11.2.x	8.13.0.x
	610 Series	AP-615	8.11.0.x	8.13.0.x
	600 Series	AP-605H	8.12.0.x	8.13.0.x
5xx	580 Series	AP-584, AP-585, AP-585EX, AP-587, AP-587EX	8.10.0.x	8.13.0.x
	570 Series	AP-574, AP-575, AP-577, AP-575EX, AP-577EX	8.7.0.x	8.13.0.x
	560 Series	AP-565, AP-567, AP-565EX, AP-567EX	8.7.1.x	8.13.0.x
	550 Series	AP-555	8.5.0.x	8.13.0.x
	530 Series	AP-534, AP-535	8.5.0.x	8.13.0.x
	510 Series	AP-518	8.7.0.x	8.13.0.x
		AP-514, AP-515	8.4.0.x	8.13.0.x
	500 Series	AP-504, AP-505	8.6.0.x	8.13.0.x
		AP-505H, AP-505HR	8.7.0.x	8.13.0.x
		AP-503H, AP-503HR	8.7.1.x	8.13.0.x
		AP-503	8.11.1.x	8.13.0.x

Access Points			AOS-8.x Versions Supported	
AP Family	AP Series	AP Model	Minimum	Latest
3xx	380 Series	AP-387	8.4.0.x	8.10.0.x
	370 Series	AP-374, AP-375, AP-377, AP-375EX, AP-377EX, AP-375ATEX	8.3.0.x	8.13.0.x
	360 Series	AP-365, AP-367	8.3.0.x	8.13.0.x
	340 Series	AP-344, AP-345	8.3.0.x	8.10.0.x
	330 Series	AP-334, AP-335	8.1.0.x	8.10.0.x
	320 Series	AP-324, AP-325	8.0.0.x	8.10.0.x
	310 Series	AP-318	8.3.0.x	8.13.0.x
		AP-314, AP-315	8.1.0.x	8.13.0.x
	300 Series	AP-304, AP-305	8.1.0.x	8.13.0.x
		AP-303H, AP-303HR	8.2.0.x	8.13.0.x
		AP-303P	8.4.0.x	8.13.0.x
		AP-303	8.3.0.x	8.13.0.x
2xx	270 Series	AP-274, AP-275, AP-277	8.0.0.x	8.10.0.x
	220 Series	AP-224, AP-225, AP-228	8.0.0.x	8.10.0.x
	210 Series	AP-214, AP-215	8.0.0.x	8.10.0.x
	200 Series	AP-207	8.1.0.x	8.10.0.x
		AP-204, AP-205, AP-205H	8.0.0.x	8.10.0.x
		AP-203H, AP-203R, AP-203RP	8.2.0.x	8.10.0.x

Access Points			AOS-8.x Versions Supported	
AP Family	AP Series	AP Model	Minimum	Latest
1xx	170 Series	AP-175AC, AP-175AC-F1, AP-175DC, AP-175DC-F1, AP-175P, AP-175P-F1	8.0.0.x	8.6.0.x
	130 Series	AP-134, AP-135	8.0.0.x	8.6.0.x
	110 Series	AP-114, AP-115	8.0.0.x	8.6.0.x
	100 Series	AP-103, AP-104, AP-105	8.0.0.x	8.6.0.x
		AP-103H	8.0.0.x	8.3.0.x
9x	90 Series	AP-92, AP-93, AP-93H	8.0.0.x	8.2.0.x

Chapter 5

Regulatory Updates in AOS-8.12.0.5

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release. Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the controller Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at networkingsupport.hpe.com.

The following DRT file version is part of this release:

- DRT-1.0_92117

Chapter 6

Resolved Issues in AOS-8.12.0.5

This chapter describes the resolved issues in this release.

Table 3: *Resolved Issues in AOS-8.12.0.5*

Bug ID	Description	Reported Version
AOS-246170 AOS-245703	The Dashboard > Overview > Wireless Clients page of the WebUI did not show accurate information. For example, some column information like IP ADDRESS and ROLE might be shown as blank, and the NAME column might wrongly display other information like the MAC ADDRESS of the client. The fix ensures that the page displays accurate information. This issue was observed in Mobility Conductors running AOS-8.10.0.6 or later versions.	AOS-8.10.0.6
AOS-246606	Under the Services > Firewall page of the WebUI, starting from the Deny all IP fragments parameter, the NVDA reader called out only parameters that were not configured. The fix adds a tabindex to make the labels for these parameters focusable, so that both checked and unchecked states of the checkboxes are read out. This issue was observed in controllers running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-247708	In some Mobility Conductors running AOS-8.11.2.0, the ZMQbg!Reaper process crashed after upgrading to AOS-8.12.0.0. The fix ensures that the Mobility Conductors work as expected.	AOS-8.11.2.0
AOS-252538	The IKE XAuth process failed on Remote APs, causing them to reboot and appear as Down on controllers. The issue occurred when users did not modify the password in the WebUI while provisioning multiple RAPs. The fix ensures the process works as expected. This issue was observed in access points running AOS-8.6.0.17 or later versions.	AOS-8.6.0.17
AOS-253616 AOS-256571	Mobility Conductors did not update AirMatch optimization. The fix ensures that the AirMatch optimization works as expected. This issue was observed in Mobility Conductors running AOS-8.10.0.10 or later versions.	AOS-8.10.0.11
AOS-254431 AOS-259912	Users experienced disconnections on hand held devices while attempting to renew the PMK cache. The issue was caused by the AP sending an unencrypted EAP identity request after receiving the start message from the user, which resulted in the user being disconnected for several minutes. The fix ensures that when the client initiates a new EAP session while being already connected, the EAP packets from the AP were sent encrypted using the current PTK, preventing disconnections. This issue was observed in APs running AOS-8.10.0.0 or later versions.	AOS-8.10.0.8
AOS-256160	When CPsec was disabled via the WebUI, users were unable to collect AP tech support logs from AP-515 access points running AOS-8.10.0.0 or later versions. The fix ensures that tech support files are collected successfully.	AOS-8.12.0.1

Table 3: Resolved Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-256180	After a software upgrade, Branch Gateways failed to reestablish a connection with peer VLANs when PAPI enhanced security was enabled. The fix ensures the Branch Gateway works as expected. This issue was observed in Central-managed gateways running AOS-8.6.0.4-2.2.0.7 or later versions.	AOS-8.6.0.15
AOS-256821	The BLE relay process crashed unexpectedly in 7220 controllers running AOS-8.10.0.11 or later versions. This issue occurred when the main BLE relay thread and the thread for the WebSocket connection were not synchronized. This caused the connection state to be removed by the main BLE thread while the WebSocket thread accessed the packet queue.	AOS-8.10.0.11
AOS-257568	Some APs unexpectedly crashed and rebooted when FTM was enabled. The log files listed the error as InternalError: : 96000210 1 SMP PC: phy_utils_write_phyreg_nopi+0x70/0x130 [wl_v6] Warm-reset . The fix ensures the APs work as expected. This issue was observed in APs running AOS-8.12.0.1 or later versions.	AOS-8.12.0.1
AOS-257808	Customers experienced leakage of per-user bandwidth contracts in controllers in a cluster setup over a period of months. This issue occurred because bandwidth contracts were not applied to connected clients. The fix ensures bandwidth contracts do not leak in cluster setups. This issue was observed in 7240XM controllers running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11
AOS-258307 AOS-260505 AOS-260341	Some controllers unexpectedly rebooted due to a race condition in the Fpapps process in Layer 2 and Layer 3 modules. The log files listed the reason as Reboot Cause: Nanny rebooted machine - fpapps process died (Intent:cause:register 34:86:50:2) . The fix ensures the controllers work as expected. This issue was observed in 7240XM controllers running AOS-8.10.0.10 or later versions.	AOS-8.10.0.10
AOS-258415	A few APs crashed and rebooted unexpectedly. The log files listed the reason as, Reboot caused by kernal Panic: Fatal exception in interrupt . The fix ensures that the APs work as expected. This issue was observed on AP-635 access points running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0
AOS-258558	In some Mobility Conductors, the total throughput usage did not match with the throughput of the individual managed devices. The sum of the managed devices was significantly higher than the one reported in the Dashboard > Overview > USAGE page of the conductor's WebUI. At the same time, the portion of the graph was concave, representing the lesser throughput. This issue was caused by the data type used in the backend to store these values. The fix ensures the USAGE data is congruent. This issue was observed in Mobility Conductors running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-258773	The 2.4GHz swept spectrogram chart displayed only the color corresponding to -90dBm for any AP in spectrum monitor mode. The fix ensures that the 2.4GHz swept spectrogram chart accurately displays the full range of signal strengths with appropriate colors. This issue was observed in APs running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0

Table 3: Resolved Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-259311 AOS-253850	Clients experience poor network performance when connecting to APs in a cluster. The fix ensures that the APs work as expected. This issue was observed in APs running AOS-8.10.0.12 or later versions.	AOS-8.10.0.12
AOS-259383 AOS-247284	Some access points randomly crashed and rebooted with signature FW assert ar_wal_tx_sch_status.c:645 Assertion (PPDU_QUEUE_ID(tx_ctxt) != TX_INVALID_QUEUE PPDU_SCH_ID(tx_ctxt) Wlan driver! ar_wal_tx_sch_status.c:645 . This issue was observed due to a FW assert caused by a mismatch in the scheduler ID. The fix ensures that the APS work as expected. This issue was observed on AP-555 access points running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-259396 AOS-258467 AOS-261527	Clients were unable to connect to 802.1x SSIDs on 630 Series access points running AOS-8.12.0.5 or later versions. The fix ensures the APs work as expected. This issue occurred when the client was not aged out for both associated and NONE-state clients.	AOS-8.12.0.5
AOS-259606	Some clients connected to a 6GHZ SSID with security mode set to enhanced-open , faced low throughput due to problems with Block Acknowledgment. The fix ensures clients get the expected throughput in this scenario. This issue was observed in APs running in AOS-8.12.0.2 or later versions.	AOS-8.12.0.2
AOS-259665	While roaming, Intel AX211 clients frequently disconnected and sent multiple deauthentication frames. The fix introduces general improvements and optimizations of low-level management frame transmission, resolving the problem. This issue was observed in AP-615 access points running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-259984 AOS-260461 AOS-261609	Users were unable to successfully roam between access points when the controller failed to initiate the 4-way handshake for the new association. This issue occurred on enhanced-open ESSIDs with MAC authentication enabled when the authentication server overrode the controller's initial VLAN assignment. The fix ensures users can roam between APs as expected. This issue was observed in controllers running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-260100 AOS-260111 AOS-260811 AOS-260961 AOS-261010 AOS-261165 AOS-261318 AOS-261464 AOS-261559	Some AP-577 access points running AOS-8.10.0.9 or later versions rebooted unexpectedly. The log files listed the reason for the reboot as BUGSoftLockup:CPU#1 stuck for 22s! [kworker/1:3:27856] PC:wlc_bmac_suspend_mac_and_wait+0x21c/0x440 [wl_v6] . The fix ensures that the APs work as expected.	AOS-8.10.0.9
AOS-260282	Users were unable to delete certain entries from the Managed Networks > Security > Denied Clients page of the WebUI. The fix ensures that the UI works as expected. This issue was observed in Mobility Conductors running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11

Table 3: Resolved Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-260317 AOS-261156	Some access points crashed and rebooted unexpectedly when multiple users were connected, and the power-saving mode was activated. The issue arose from dropped packets due to insufficient capacity in the power save queue, resulting in AP crashes. The fix ensures the APs work as expected. This issue was observed in APs running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-260391	High channel utilization and interference was observed on all 2.4 GHz channels. Clients were unable to connect with 2.4 GHz when channel utilization was high. The fix ensures that clients are able to connect on the 2.4 GHz channel. This issue was observed in AP-635 access points running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0
AOS-260437	Some users connected to an SSID configured with WPA3-AES-CCM-128 encryption experienced intermittent traffic issues after roaming between APs. The issue persisted until users roamed to another AP, at which point traffic resumed. The fix ensures that user traffic can pass after a station roams. This issue was observed on access points running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-260448	Some RAPs using WPA3 did not remove clients from the association table. The fix ensures clients are correctly removed. This issue was observed in RAPs running AOS-8.12.0.2 or later versions.	AOS-8.12.0.2
AOS-260527	In non-CPsec environments, obtaining technical support logs either via the WebUI or the show ap tech-support command took a long time, sometimes resulting in the process being aborted or an Unable to save..!! error message being displayed. The issue was related to the show memory ap rapper command taking too long to run whenever CPsec was disabled, delaying the request. The fix ensures the expected behavior when checking rapper memory in a non-CPsec environment, expediting the generation of technical support logs. This issue was observed in managed devices running AOS-8.10.0.0 or later versions.	AOS-8.12.0.1
AOS-261118 AOS-261119	During a cluster failover, AP-635 and AP-535 access points went down and did not come back up. The issue occurred in a two-node cluster where the AP's Standby Active Access Controller (SAAC) was slow to be assigned. The node that would become the SAAC initially acted as the Unicast Access Controller (UAC) for the AP. If the AP failed over to this node as the Active Access Controller (AAC), the node continued to consider itself the UAC. Upon failover completion, the node attempted to exit the UAC role, mistakenly deleting the AP's tunnel and causing the AP to go offline. The fix ensures that APs recover and come back online automatically after a cluster failover. This issue was observed on devices running AOS-8.10.0.12 or later versions.	AOS-8.10.0.12
AOS-261352	Some gateways reported multiple route-cache allocation failures causing clients to be unable to connect through Wi-Fi. The issue occurred due to memory corruption. The fix ensures that the memory corruption is resolved. Hence, the route-cache table will not be full, resulting in seamless client connectivity. This issue was observed in gateways running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14

Table 3: Resolved Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-261430	Clients experienced traffic drops and disconnections while roaming in high density environments. The log files listed the error as tx_flush_err_tx_stall_war . This issue occurred on both dot1x and Open SSIDs protocols on 5 GHz radios. The fix ensures clients can connect seamlessly. This issue was observed in AP-534, AP-585, and AP-654 access points running AOS-8.12.0.3 or later versions.	AOS-8.12.0.3
AOS-261440	The ANI feature was disabled for some AP-535 access points running AOS-8.10.0.15 or later versions. This issue occurred due to consistently high PHY error rates disabling ANI. The fix ensures that the ANI feature works as expected.	AOS-8.10.0.15
AOS-261483	The airmatch ap freeze command was unable to freeze channel 165 on the controller. The fix ensures the command works as expected. This issue was observed in AP-535 access points running AOS-8.10.0.15 or later versions.	AOS-8.10.0.15
AOS-261520	Some APs crashed and rebooted unexpectedly after a VAP was removed. The log files listed the reason for the crash as BadPtr:0000030c PC:w1_pktc_tx+0x1d8/0x798 [w1_v6] Warm-reset . The fix ensures there will be no crashes associated with removing VAPs. This issue was observed in AP-505 access points running AOS-8.10.0.6 or later versions.	AOS-8.10.0.6
AOS-261578	Some APs remained on old channel even after detecting radar. The fix ensures that the APs work as expected. This issue was observed in AP-515 running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-261623 AOS-261987 AOS-261992 AOS-262042	Some AP-555 access points randomly crashed and rebooted. The log files listed the reason for the crash as Kernel panic - not syncing: Take care of the TARGET ASSERT . The fix ensures APs work as expected. This issue was observed in APs running AOS-8.10.0.12 or later versions.	AOS-8.10.0.12
AOS-261677	Hidden SSIDs responded incorrectly to probe requests. The fix ensures the hidden SSIDs do not respond in this scenario. This issue was observed in AP-635 and AP-655 access points running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0
AOS-261753	Some access points failed their uplink 802.1x authentication. The log files listed the reason for the event as Failed(-1-256) to sign hash using TPM dev . The fix ensures that the APs authenticate successfully. This issue was observed in AP-305 running AOS-8.12.0.3 or later versions.	AOS-8.12.0.3
AOS-261852 AOS-261583	In a managed devices cluster with wired AirGroup server enabled, packets transmitted on the uplink of one controller are revived with the MAC address of the other controller. The fix ensures that the controllers work as expected. This issue was observed in the Mobility Conductors or controllers running AOS-8.10.0.9 or later versions.	AOS-8.10.0.9
AOS-261922 AOS-262596	Some AP-615 access points displayed SSIDs that were not configured. The fix ensures that the APs work as expected. This issue was observed in APs running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0

Table 3: Resolved Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-261973	Some APs crashed and rebooted unexpectedly. The log files listed the reason as kernel panic: Fatal exception in interrupt . The fix ensures the APs work as expected. This issue was observed in AP-635 access points running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0
AOS-262133	Some APs crashed and rebooted unexpectedly. The log files listed the reason as PC is wl_handle_blog_emit+0x14/0x94 . The fix ensures the APs work as expected. This issue was observed in access points running AOS-8.12.0.3 or later versions.	AOS-8.x.x.x
AOS-262158	Some AP-515 access points randomly crashed and rebooted. The log files listed the reason for the crash as BadPtr:00000036 PC:wlc_taf_pktfree_check+0x1b58/0x6140 [wl_v6] Warm-reset . The fix ensures APs work as expected. This issue was observed in APs running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-262273	After upgrading to AOS-8.12.0.3, some clients roaming between tunnel-mode and bridge-mode using the same ESSID caused the authmgr process to crash. The fix ensures client roaming works as expected. This issue was observed in controllers running AOS-8.12.0.3 or later versions.	AOS-8.12.0.3
AOS-262403 AOS-261409 AOS-261914	Some clients connected to 500 Series access points experienced latency and performance issues. The fix brings back the latency and performance to the expected level for these clients. This issue was observed in access points running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-262764	AirGroup servers were unable to be discovered by clients in some cases. The issue occurred due to a crash in the MDNS process when clients or servers advertise MDNS services with maximum allowable hostname length. The fix ensures the controllers work as expected. This issue was observed in XLP based controllers running AOS-8.12.0.3 or later versions.	AOS-8.12.0.3
AOS-263421	After running the tar logs tech-support command, a timestamp is displayed before capturing all the commands' outputs. However, upon issuing a show command, the timestamp kept displaying at the controller level. The fix ensures the clock cli-timestamp is disabled after the logs tech-support command is completed. The issue was observed in gateways running AOS-8.12.0.0 or later versions.	AOS-8.12.0.0
AOS-260486	After upgrading to AOS-8.10.0.11, some users experienced connection issues on devices connected to APs due to the AirMatch optimization process. The issue occurred in rare cases during the initial optimization runs, when AirMatch failed to read previously optimized radio data. As a result, the optimization process was triggered the following day, displaying a New radios optimized message, which led to unnecessary deployments, particularly when the quality-threshold value was not met. The fix ensures that the AirMatch optimization process correctly reads the optimized radio data from prior runs during the initial optimization process and ensures deployment according to the quality-threshold. This issue was observed in AP-315 and AP-515 access points running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11

Chapter 7

Known Issues in AOS-8.12.0.5

This chapter describes the known issues observed in this release.

Table 4: *Known Issues in AOS-8.12.0.5*

Bug ID	Description	Reported Version
AOS-233582	The licensing server fails to update the IP address of the secondary Mobility Conductor. This issue occurs when the secondary Mobility Conductor becomes the primary Mobility Conductor. This issue is observed in managed devices running AOS-8.6.0.11 or later versions.	AOS-8.6.0.11
AOS-239836 AOS-239952 AOS-241189	The Nbapi-Helper process crashes in some Mobility Controllers running AOS-8.10.0.2 or later versions. This prevents users from obtaining the feed from the Analytics and Locations Engine (ALE) servers.	AOS-8.10.0.7
AOS-242425	The show transceiver command incorrectly displays the Aruba Certified field as NO due to a missing entry in the supported SFP+ database. This issue is observed in controllers running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-244193	Some AP-655 access points frequently bootstrap due to an interoperability issue of the APs firmware with certain third-party switches. The issue is observed in APs running AOS-8.10.0.6 or later versions.	AOS-8.10.0.6
AOS-245600 AOS-252206 AOS-255808	Some controllers crash unexpectedly due to a memory leak in the DDS process. This issue is observed in controllers running AOS-8.6.0.17 or later versions.	AOS-8.10.0.8
AOS-248282	7010 controllers display PVST+ issues where the removal of VLANs leads to the incorrect transmission of PVST+ BPDUs with both PVID and 802.1Q VLAN ID set to 0 . This issue is observed in controllers running AOS-8.6.0.10 or later versions.	AOS-8.6.0.10
AOS-248739	Some WLAN SSIDs are not displayed under the Configuration > WLANs section of the WebUI. This issue is observed in Mobility Conductors running AOS-8.0.0.0 or later versions.	AOS-8.10.0.7
AOS-248958	Some AP-315 access points are detecting false radars. The radar log files list the radars with typeid 37 and typeid 34 . The issue is observed in APs running AOS-8.7.1.7 or later versions.	AOS-8.7.1.7
AOS-250031 AOS-251210	After upgrading to AOS-8.10.0.9, some managed devices are not able to retrieve user-table information via API calls when using the show user-table command. This issue is observed in managed devices running AOS-8.10.0.9 or later versions.	AOS-8.10.0.9
AOS-251090	When using the show boot upgrade-history command, the image upgrade history is not displayed for upgrades done through the WebUI. This issue is observed in controllers running AOS-8.10.0.8 or later versions.	AOS-8.10.0.8

Table 4: Known Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-251921	Some access points might reboot when provisioned as Remote APs. The logs list the reboot reason as AP Reboot reason: BadAddr:ffffffc040000000 PC:avs_status+0xf0c/0xf50 [wl_v6] Warm-reset . This issue is observed in AP-518 access points running AOS-8.10.0.9-FIPS or later versions.	AOS-8.10.0.9
AOS-252442 AOS-256063 AOS-256177 AOS-257450	Some APs crash and reboot unexpectedly. The log files list the reason for the event as FW assert count 1 collected 0 Send PC:0x00000000 to Wlan driver . The issue is observed in AP-535 and AP-635 access points running AOS-8.10.0.9 or later versions.	AOS-8.10.0.9
AOS-252888	In some controllers, a list index out of range exception error is seen when a netdestination alias is configured. This issue is observed in controllers running AOS-8.10.0.9 or later versions.	AOS-8.10.0.9
AOS-253118	When the software is upgraded from AOS-8.9.0.0 to AOS-8.10.0.8 or later versions, the telemetry WebSocket transport profile connection reports 50% less data. This issue is observed in managed devices running AOS-8.10.0.8 or later versions.	AOS-8.10.0.8
AOS-253145	The IP address field is accepting invalid values while configuring net-destination from the Mobility Conductor's UI under Managed Network > Configuration > Alert & Policies > Aliases . This issue is observed on Mobility Conductor running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11
AOS-253517	In some 7210 controllers, the logo is not loading when using internal captive portal with authentication. The controller displays an HTTP code 404 - not found error message. The issue is observed in controllers running AOS-8.10.0.8 or later versions.	AOS-8.10.0.8
AOS-253534	Users are unable to establish TCP sessions through port 8443. This issue occurs after the SLB process crashes due to traffic with ESI groups hitting mismatched ACL rules. This issue is observed in APs running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-254784	When clients connect to an AP, the AP generates the following error log: <ERRS> AP KAKAO-AP-A03F-R16@172.20.4.104 stm ap Unexpected stm (Station management) runtime error at handle_assoc_req, 7378, handle_assoc_req: sa-mac:a4:75:b9:d7:3d:d2, aid:59(LE:0xc03c) >= 60 or 1024, driver-val:60 . This issue occurs when the 6 GHz radio is enabled. This issue is observed in APs running AOS-8.10.0.10 or later versions.	AOS-8.10.0.10
AOS-255629	The bandwidth contract profile reference is not updated correctly when used in other profiles, such as role or user. This issue is observed in managed devices running AOS-8.10.0.7 or later versions.	AOS-8.10.0.7
AOS-255909	Some APs crash and reboot with reason AP rebooted caused by internal watchdog reset . This error is related to the driver image on the device. This issue is observed in AP-535 and AP-655 access points running AOS-8.10.0.11 or later versions.	AOS-8.10.0.11
AOS-256229	Default roles on some controllers, such as the authenticated role, are lost after enabling the PEF feature. This occurs because the role configurations are not retained when the feature is enabled. This issue is observed in controllers running AOS-8.10.0.9 or later versions.	AOS-8.10.0.9

Table 4: Known Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
	Workaround: After performing a write erase operation, enable the PEF feature and reload the controller to ensure that the default roles are initialized properly. This workaround is also applicable whenever the PEF license is used on the controller for the first time.	
AOS-256350	Some Mobility Conductors in active or standby mode running AOS-8.10.0.11 or later versions do not display data on the Dashboard > Overview > Clients page of the WebUI.	AOS-8.10.0.11
AOS-256471	Some Mobility Conductors running AOS-8.10.0.12 or later versions experience slow loading times when trying to configure any profile through the WebUI.	AOS-8.10.0.12
AOS-256745	In the Configuration > System > Profiles page of the WebUI, the landscape scroll bar cannot be dragged. This issue is observed in controllers running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-257588	Some APs do not age out clients although the station ageout timer parameter is configured to the default value of 1000 seconds. This issue is observed in AP-535 access points running AOS-8.10.0.10 or later versions.	AOS-8.10.0.12
AOS-257760	The authentication server name appears duplicated with the duplicate text overlapping the existing text. This issue occurs sometimes when a new server is configured on the WLAN profile during asynchronous operations. This issue is observed in controllers running AOS-8.10.0.0 or later versions.	AOS-8.10.0.12
AOS-258685	When creating a new VLAN, the VLAN ID is not set to Hash by default, under Configuration > Interfaces > VLANs > Options > Assignment Type . However, in the output of the show vlan mapping command, the Assignment Type shows Hash as expected. In the WebUI, when the Assignment Type is actually selected and the changes are saved, the Assignment Type is shown correctly in the controller and Mobility Conductor. This issue is observed in controllers running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-258720 AOS-259805	Some controllers unexpectedly crash and reboot. The log files list the reason as Reboot Cause: Datapath timeout , which occurs when a packet with an invalid IP header reaches the controller. This issue is observed in 9240 controllers running AOS-8.10.0.8 or later versions.	AOS-8.10.0.8
AOS-258777	Some users experience synchronization issues between controllers and RAPs after updating the RAPs' allowlist. The issue occurs when modifying the AP-Group or AP-Name , which is correctly updated on the RAP but not on the controller. This issue is observed in 7220 controllers running AOS-8.10.0.11 or later versions.	AOS-8.10.0.13
AOS-259078	By design, a capacity license cannot be added through the WebUI whenever an external license server is configured. However, the Configuration > License > Capacity License tab is visible. This issue is observed in managed devices running AOS-8.10.0.0 or later versions. Note: Capacity licenses should be added through the CLI of managed devices.	AOS-8.10.0.0

Table 4: Known Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-259493	Some DPI-enabled 7205 controllers running AOS-8.10.0.14 or later versions crash and reboot unexpectedly. Log files list the reason for the event as Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2) .	AOS-8.10.0.14
AOS-259552 AOS-261151	When a VPN is configured for the DHCP proxy on controllers, the IP address gets printed in reverse order. This issue is observed in gateways running AOS-8.10.0.13 or later versions.	AOS-8.10.0.13
AOS-259603 AOS-260283 AOS-260347	The ZMQ threads of the nbapi_helper process crash randomly. This issue is observed in Mobility Conductors after upgrading the software to AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-260012	Under the Dashboard > Configuration > Roles & Policies > Roles page, the RULES field incorrectly displays -- when Policy-Based Routing is enabled. This issue occurs because of a case mismatch between the policy names received from the API. This issue is observed in managed devices running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-260160	In some Mobility Conductors running AOS-8.11.2.2 or later versions, the IP address of several clients is not displayed in Dashboard > Overview > Clients in the WebUI . The IP addresses do show in up in the CLI and in the managed devices.	AOS-8.11.2.2
AOS-260519	Stale entries are not cleared in the WebUI when the clear gap-db command is executed for the AP. This issue occurs due to the SC-MON process not being able to clear down AP entries successfully. This issue is observed in APs running AOS-8.10.0.6 or later versions.	AOS-8.10.0.6
AOS-260698	In some 9240 gateways, adding a capacity license in the WebUI fails if the key contains a plus sign (+). Verifying the license in the CLI also reveals the license is not installed. However, installing the license directly in the CLI works as expected. This issue is observed in controller running AOS-8 10.0.11 or later versions.	AOS-8.10.0.11
AOS-260766 AOS-261350	Some APS are down after the controller is upgraded to AOS-8.10.0.11 or later. This issue occurs when a user's VLAN is not part of any physical interface resulting in a DDS spike. This issue is observed in APs running AOS-8.10.0.11 or later versions.	AOS-8.10.0.13
AOS-260852	VAPs are turned off and cannot be turned back on after adding a new controller to the cluster. The issue occurs due to an incorrect configuration of the node limit in the MultiZone profile. This issue is observed in AP-655 access points running AOS-8.10.0.0 or later versions.	AOS-8.10.0.0
AOS-260880	In 9240 gateways, when configuring a VPN IP over DHCP proxy option, users are unable to connect to the VPN. This issue is observed in gateways running AOS-8.10.0.1 or later versions.	AOS-8.10.0.1
AOS-261107	The LLDP information is not displayed in WebUI for some access points but is displayed correctly in the CLI code. The issue is observed in APs running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-261182 AOS-260978 AOS-261903	The nbapi_helper process crashes unexpectedly on standby Mobility Conductor running AOS-8.10.0.13, or later versions. This issue occurs under demanding loads.	AOS-8.10.0.13

Table 4: Known Issues in AOS-8.12.0.5

Bug ID	Description	Reported Version
AOS-262289 AOS-262472 AOS-262500 AOS-262678 AOS-263164 AOS-261725		
AOS-261426	The serpappstart process crashes in some 7210 controllers running AOS-8.10.0.12 or later versions. Workaround: Increase the waiting/sync time and configure the nanny process to restart serpappstart .	AOS-8.10.0.12
AOS-261646	The output of the show ip dhcp statistics command shows abnormal results. The issue occurs due to an invalid variable declaration. This issue is observed in controllers running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-261697	Users are unable to upload custom HTML files to the captive portal. An error #incomplete command error is displayed on the portal when the custom report is uploaded and changes are submitted. This issue is observed in devices running AOS-8.12.0.2 or later versions.	AOS-8.12.0.2
AOS-261945	The Dhcpdwrap process crashed and rebooted unexpectedly. The log files listed the reason for the reboot as x86-manuf.c(276): ReadEeprom failed . The fix ensures that the Mobility Conductors work as expected. This issue was observed in Mobility Conductors running AOS-8.12.0.5 or later versions.	AOS-8.10.0.14
AOS-262031	On warm start (wlsxWarmStart) or cold start (wlsxColdStart) of gateways, the Aruba WLSX-TRAP-MIB defined traps are not sent, but the standard SNMPv2-MIB traps (warmStart, coldStart) are sent correctly. This issue is observed in controllers running AOS-8.10.0.12 or later versions.	AOS-8.10.0.12
AOS-262395	The UCM module in controllers restarted multiple times due to the wrong mapping of ALGs. This issue is observed on controllers running AOS-8.10.0.14 or later versions.	AOS-8.10.0.14
AOS-262497	SHA-512 encryption is not supported in DDNS, causing issues with services like Infoblox. This issue is observed in devices running AOS-8.10.0.0 or later versions.	AOS-8.10.0.11

Chapter 8

Limitations in AOS-8.12.x

This section includes the known limitations in 8.12.x.x releases.

Title	Description
Port-Channel Limitation in 7280 Controllers	<p>The 7280 hardware architecture consists of two Network Acceleration Engines (NAEs). The ethernet ports are split between the NAEs according to this mapping:</p> <ul style="list-style-type: none">■ NAE 0: Ports 0/0/4 to 0/0/7 and 0/0/12 to 0/0/15■ NAE 1: Ports 0/0/0 to 0/0/3 and 0/0/8 to 0/0/11 <p>When configuring a port-channel, it is recommended that member ports are distributed between the two different NAEs (e.g., 0/0/0 and 0/0/4). This is to ensure hitless operation if one of the member ports experiences a link flap either due to a network event or a user-driven action. If member ports are on the same NAE, a link flap will be observed for less than a second. It is not recommended to form a 10 Gbe based port-channel larger than 2x 10 Gbe due to this hardware limitation.</p>
cpboot command in 7000 Series and 7200 Series Controllers	<p>The cpboot command does not upgrade the AOS-8 software version of 7000 Series and 7200 Series controllers.</p>
VAP Limitation on Access Point Platforms	<p>When performing configuration changes on one VAP, clients associated to other non-modified VAPs may lose connectivity. This issue is observed in Broadcom-based 340 Series, 500 Series, and 600 Series access points running AOS-8.3.0.0 or later versions. For more information, contact support and make reference to bug ID AOS-131599.</p>

Chapter 9

Upgrade Procedure

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor , managed device, or stand-alone controller.

Important Points to Remember

To upgrade your managed device or Mobility Conductor :

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
 - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
 - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
 - What version of AOS-8 runs on your managed device?
 - Are all managed devices running the same version of AOS-8?
 - What services are used on your managed device (employee wireless, guest access, Remote AP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load AOS-8 images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-8, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Aruba Mobility Conductor Licensing Guide*.
- Multiversion is supported in a topology where the managed devices are running the same version as the Mobility Conductor , or two versions lower. For example multiversion is supported if a Mobility Conductor is running AOS-8.5.0.0 and the managed devices are running AOS-8.5.0.0, AOS-8.4.0.0, or AOS-8.3.0.0.

RAM and FLASH Storage Requirements

All Aruba managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Ensure sufficient RAM and flash space is available in the Controller/MD/BGW before proceeding with the upgrade.
- Execute the **show memory** command to identify the available free memory.
- Execute the **show storage** command to identify the available flash space.
- If the output of the **show storage** command indicates that there is insufficient flash RAM, free some used memory. Copy any log files, crash data, or flash backups from your gateways to a desired location. Delete the following files from the Controller/MD/BGW to free FLASH storage:
 - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 31](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
 - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 31](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
 - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 31](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.
- The show commands are available under **Analyze > Tool > Commands** section of Aruba Central.

If available RAM is not sufficient to meet the requirements stated in the appropriate release notes, it may be necessary to reboot the device and then immediately upgrade, or disable some functionality. The user should consult HPE/Aruba technical support for guidance.



In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

Deleting a File

You can delete a file using the WebUI or CLI.

In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

In the CLI

```
(host) #delete filename <filename>
```

Low Free Flash Memory

Sometimes, after extended use, the flash memory might get used up for logs and other files. The AOS-8 image has increased in size and this may cause issues while upgrading to newer AOS-8 images without cleaning up the flash memory.

Prerequisites

Before you proceed with the freeing up the flash memory:

- Ensure to always backup the configuration and flash memory. Issue the **backup configuration** and **backup flash** commands to backup the configuration and flash.
- Copy the **flashbackup.tar.gz** and **configbackup.tar.gz** files out of the controller. Then delete the **flashbackup.tar.gz** and **configbackup.tar.gz** files from the flash memory of the controller.
- Use only one partition for the upgrade activity and keep the other partition unchanged.

If you use the WebUI to perform an upgrade, a banner on the **Maintenance** page provides the following reminder to have sufficient free flash memory before initiating an upgrade.

For a healthy and stable system it requires free space of 360 MB for AOS v8.3 and 8.5, 570 MB for AOS 8.6 and 8.7 and 450 MB for AOS 8.8 and higher version in the /flash directory. Please make sure minimum required memory is available in /flash before upgrading to newer version.

Freeing up Flash Memory

The following steps describe how to free up the flash memory before upgrading:

1. Check if the available memory in **/flash** is greater than the limits listed in [Table 5](#) for all supported controller models:

Table 5: *Flash Memory Requirements*

Upgrading from	Upgrading to	Minimum Required Free Flash Memory Before Initiating an Upgrade
8.3.x	8.12.x	360 MB
8.5.x	8.12.x	360 MB
8.6.x	8.12.x	570 MB
8.7.x	8.12.x	570 MB
8.8.x and above	8.12.x	450 MB

To check the available free flash memory, issue the **show storage** command. Following is the sample output from a controller with low free flash memory:

```
(host) [mynode] #show storage
Filesystem      Size      Available      Use      %      Mounted on
/dev/usb/flash3 1.4G      1014.2M      386.7M    72%    /flash
```

2. If the available free flash memory is less than the limits listed in [Table 5](#), issue the following commands to free up more memory.
 - **tar crash**
 - **tar clean crash**
 - **tar clean logs**
 - **tar clean traces**
3. Issue the **show storage** command again to check if the available space in **/flash** is more than the minimum space required for AOS-8 upgrade as listed in [Table 5](#)

4. **If you are unable to free up sufficient flash memory, contact Technical Support. Do not reboot the controller.**
5. If sufficient flash memory is available, proceed with the standard AOS-8 upgrade. See [Upgrading AOS-8](#).
6. If a reboot was performed, you may see some of the following errors. Follow the directions below:
 - Upgrade using standard procedure. You may see some of the following errors:
Error upgrading image: Ancillary unpack failed with tar error (tar: Short header).
Please clean up the /flash and try upgrade again.
Error upgrading image: Ancillary unpack failed with tar error (tar: Invalid tar magic).
Please clean up the /flash and try upgrade again.
Error upgrading image: Need atleast XXX MB space in /flash for image upgrade, please clean up the /flash and try upgrade again.
Failed updating: [upgradelImageNew.c] extractAncTar (dev: /dev/usb/flash1 imgLoc: /flash/config/ArubaOS_70xx_8.8.0.0-mm-dev_78066
 - If any of the above errors occur, issue the **show image version** command to check for the default boot partition. The partition which was upgraded should become the default partition. Following is the sample output of the **show image version** command:

```
(host) [mynode] #show image version
```

```
-----
Partition           : 0:0 (/dev/usb/flash1) **Default boot**
Software Version     : AOS-8.9.0.0 (Digitally Signed SHA1/SHA256 - Production
Build)
Build number        : 81046
Label               : 81046
Built on            : Thu Aug 5 22:54:49 PDT 2021
-----
Partition           : 0:1 (/dev/usb/flash2)
Software Version     : AOS-8.7.0.0-2.3.1.0 (Digitally Signed SHA1/SHA256 -
Developer/Internal Build)
Build number        : 0000
Label               : arpitg@sdwan-2.3_arpitg-3-ENG.0000
Built on            : Tue Aug 10 15:02:15 IST 2021
-----
```

- If the default boot partition is not the same as the one where you performed the upgrade, change the default boot partition. Issue the **boot system partition <part_number>** command to change the default boot partition. Enter **0** or **1** for **part_number** representing partition 0:0 or partition 0:1, respectively.
- Reload the controller. If any of the errors listed in step 4 were observed, the following errors might occur while booting AOS-8.9.0.0.

Sample error:

```
[03:17:17]:Installing ancillary FS [ OK ]
Performing integrity check on ancillary partition 1 [ FAIL : Validating new
ancillary partition 1...Image Integrity check failed for file
/flash/img1/mswitch/sap/arm32.ari. Digest Mismatch]
Extracting Webui files..tar: Short read
chown: /mswitch/webui/*: No such file or directory
chmod: /mswitch/webui/wms/wms.cgi: No such file or directory
```

- After the controller reboots, the login prompt displays the following banner:

```
*****
* WARNING: An additional image upgrade is required to complete the *
* installation of the AP and WebUI files. Please upgrade the boot *
* partition again and reload the controller. *
*****
```

- Repeat steps 1 through 5. If sufficient free flash memory is available, proceed with the standard AOS-8 upgrade procedure. See [Upgrading AOS-8](#).
- If sufficient free flash memory is not available, issue the **dir** and **dir flash** commands to identify large files occupying the flash memory.



-
- Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.
-

Issue the **delete filename <filename>** command to delete large files to free more flash memory.

- Check if sufficient flash memory is free as listed in [Table 5](#).
- Proceed with the standard AOS-8 upgrade procedure in the same partition. See [Upgrading AOS-8](#).

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
```

Please wait while we take the flash backup.....

File flashbackup.tar.gz created successfully on flash.

Please copy it out of the controller and delete it when done.

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword>  
<remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
```

Please wait while we restore the flash backup.....

Flash restored successfully.

Please reload (reboot) the controller for the new files to take effect.

Upgrading AOS-8

Upgrade AOS-8 using the WebUI or CLI.



Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [RAM and FLASH Storage Requirements on page 27](#).



When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed ccurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

In the WebUI

The following steps describe how to upgrade AOS-8 from a TFTP server, FTP server, or local file.

1. Download the AOS-8 image from the customer support site.
2. Upload the AOS-8 image to a PC or workstation on your network.
3. Validate the SHA hash for the AOS-8 image:
 - a. Download the **Aruba.sha256** file from the download directory.
 - b. Load the AOS-8 image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the customer support site.



The AOS-8 image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted AOS-8 image.

4. Log in to the AOS-8 WebUI from the Mobility Conductor .
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
 - a. Select the **Local File** option from the **Upgrade using** drop-down list.
 - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

In the CLI

The following steps describe how to upgrade AOS-8 from a TFTP server, FTP server, or local file.

1. Download the AOS-8 image from the customer support site.
2. Open an SSH session to your Mobility Conductor .
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-8 image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

7. Reboot the Mobility Conductor .

```
(host)#reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

Verifying the AOS-8 Upgrade

Verify the AOS-8 upgrade in the WebUI or CLI.

In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-8 image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 31](#) for information on creating a backup.

In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the AOS-8 image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 31](#) for information on creating a backup.

Downgrading AOS-8

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade AOS-8 version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 31](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade AOS-8 version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the AOS-8 version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-8 version and configuration files.

5. After switching the boot partition, perform the following steps:

- Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the AOS-8 flash backup file.
- Do not import the WMS database.
- If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-8 version.
- If any new certificates were added in the upgraded AOS-8 version, reinstall these certificates in the downgraded AOS-8 version.

Downgrade AOS-8 version using the WebUI or CLI.

In the WebUI

The following steps describe how to downgrade the AOS-8 version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
 - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
 - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
 - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-8 version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-8 version is not stored on your system partition, load it into the backup system partition by performing the following steps:

You cannot load a new image into the active system partition.



- a. Enter the FTP or TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Enable **Reboot Controller after upgrade**.
 - d. Click **Upgrade**.
3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.
- The Mobility Conductor or managed device reboots after the countdown period.
4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-8 version by navigating to the **Maintenance > Software Management > About** page.

In the CLI

The following steps describe how to downgrade the AOS-8 version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```
2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```
3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-8 version is stored.

```
(host) #show image version
```



You cannot load a new image into the active system partition.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```
5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```
6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-8 version.

```
(host) # show image version
```

Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.